

Evaluation Report for the Amphenol-Bendix 453 Miniature Circular Connector with Mil-T-29504 Optical Termini in a Vibration Environment

Jeannette Plante

July 1995

- **Abstract**
- **1.0 Introduction**
- **2.0 Objective**
- **3.0 Parts Description**
- **4.0 Test Program**
- **5.0 Test Results and Discussion**
 - **5.2 Thermal Conditioning**
 - **5.3 Thermal Cycling Test**

- **5.4 The First Vibration Test - Thick Bracket**

- **5.4.1 Visual Examination Following First Vibration Test**

- **5.4.2 Optical Measurements Following First Vibration Test (Vibration 1)**

- **5.5 Supplemental Testing: A Second Vibration Test Using the Thin Bracket**

- **6.0 Conclusions**

- **7.0 Recommendations**

- **8.0 Acknowledgments**

- **APPENDIX A**

- **Index**

- **A1 Table I. Parts Ratings**

- **A2 Test Method for Insertion Loss/Optical Throughput**

- **Table II. Interferometer Measurement Results**

- **Table III. Initial Visual 400X**

- **Table IV. Baseline Insertion Loss and Optical Throughput Data**

- **Table V. Data for First Vibration Test- Thick Bracket**

- **Table VI. Data for Second Vibration Test - Thin Bracket**



[Up to TVA Homepage](#)




[Back to the Library](#)

Webster: Melanie.Ott@gsfc.nasa.gov

Abstract

The use of a multi-termini optical connector has been adopted on two GSFC programs. This connector system introduces the use of individually removable, specially polished, physically touching, optical contacts. This evaluation addresses performance of the Amphenol-Bendix "453" connector using optical contacts in a random vibration environment. The results show that this multi-termini connector performs within the manufacturer's specifications to at least 37 Grms random vibration, with thermal cycling preconditioning. Contamination was found to be generated by the connector itself, indicating the need for attention to cleanliness and the development of adequate cleaning procedures. Alignment sleeve retention force played a role in the occurrence of metal filing contamination between one of the optical contact pairs, indicating that alignment sleeve retention force should be more closely controlled. Finally, the optical contacts with less than ideal polish qualities tended to degrade over the duration of the evaluation which indicates that cleave and polish damage can lead to increased polish surface defects over the life of the optical connector. While the "453" connector was found suitable for use in environments that experience mild thermal cycling, further study of the relationship between the surface polish defects, temperature and fiber tension will show their suitability for use in more thermally stressful environments.

Table of Contents



[Next Section](#)



[Up to TVA Homepage](#)




[Back to the Library](#)

Webster: Melanie.Ott@gsfc.nasa.gov

1.0 Introduction

The MIL-STD-1773 optical fiber based communication bus has been qualified and successfully flown by GSFC on the SAMPEX (Solar Anomalous Magnetospheric Particle Explorer) satellite. The success of SAMPEX has led to acceptance of the MIL-STD-1773 data bus system in the XTE (X-ray Timing Experiment) satellite and on TRMM (Tropical Rainfall Measuring Mission). Each of these later projects have been able to improve on the SAMPEX bus design by modifying various parts of the system hardware. With the exception of the "453" connector and the M29504 optical termini that is described here (Figure 1 and 2), the basic passive optical components (the fiber, cable, star coupler1), have not changed.

Figure 1. "453" - M29504 Connector System




The "453" - M29504 connection system can be used to replace multiple, individual, MIL-C-83522, SMA type, single fiber connectors. This approach should improve reliability and performance by decreasing the number of individually mating connectors and by introducing a physically contacting (PC) mate at the fiber ends. SMA connectors allow an air gap between the fiber ends which limits the performance to the air gap loss (typically 0.34 dB to 2.0 dB depending on the width of separation between the fiber ends). The M29504 termini are designed and polished to eliminate the air gap between the fiber ends.

The use of "453" connectors with several optical contacts provides smaller footprint and significant reduction in hardware weight. The XTE and TRMM busses use "453" connectors with four and sixteen optical contacts. SMA

connectors are still used in these systems at the active device interfaces (transmitters and receivers).

1/ Part numbers for the optical components used in the MIL-STD-1773 fiber optic bus are listed in section 51 of the GSFC Preferred Parts List, PPL-21. Design changes have been made on the transceiver unit for the TRMM mission.

Figure 2. Connector and Terminus



The "453" connector has a long history of use at GSFC for electrical applications. M29504 contacts in MIL-C-38999 connectors (military version of the 453) have been studied by such organizations as NASA-JSC's Space Station group, the Air Force's F22/Comanche Helicopter fiber optic development group and Martin Marietta Space Systems in Denver, however the actual use of "453" connectors in high reliability optical systems has been limited. These organizations have reported good performance for the MIL-C-38999 - M29504 connector with some uncertainty in the vibration area. To date, test data has not been released by these organizations because the connector, used as an optical device, is fairly difficult to test with respect to accuracy and repeatability.

Table of Contents



[Next Section](#)



[Up to TVA Homepage](#)



[Back to the Library](#)

Webster: Melanie.Ott@gsfc.nasa.gov



2.0 Objective

This evaluation was done to generate performance data for the "453" - M29504 system with respect to the operational requirements and application conditions of the XTE and TRMM programs. The affect of vibration on connector performance characteristics is a significant reliability concern. Another area of interest was characterization of the physical condition of the specially polished fiber ends, since XTE and TRMM were the first to use PC polished optical contacts.

Table of Contents



[Next Section](#)



[Up to TVA Homepage](#)



[Back to the Library](#)

Webster: Melanie.Ott@gsfc.nasa.gov 

3.0 Part Description

The "453" connector is Amphenol-Bendix's high reliability miniature circular connector made to the performance and dimensional specifications of MIL-C-38999, the military's specification for electrical, miniature, circular, connectors. Amphenol-Bendix's "453" was designed for NASA applications with "low outgassing" materials. It is defined as environmental class (removable contacts, non-hermetic) and scoop-proof, triple start, self-locking, threaded coupling style (a.k.a. Series III) with a wall mount flanged receptacle (the connector mating occurs on the other side of the panel to which the receptacle is attached). The metal shells are electroless nickel plated aluminum. Various polymers make up the contact insert, gasket, grommet and spacer. Standard military backshells can be used with the "453" connector. In this evaluation, both a straight saddle-clamp type and a straight backshell with auxiliary grommet were used.

The M29504 optical termini conform to the MIL-T-29504/4 and /5 specifications. These termini are designed to fit in the contact cavities of the MIL-C-38999 connector as securely and reliably as size 16, MIL-C-39029 electrical contacts. MIL-T-29504/4 and /5 specifically reference MIL-C-38999 as the corresponding connector for these termini. The termini are designed with a stainless steel body and ceramic ferrule. The ceramic ferrule retains and precisely aligns the bare fiber. The fiber is captivated by heat cured epoxy in the ferrule and the rest of the optical cable components, such as the jacket and strength members, are captured by the terminus crimp sleeve and heat shrink tubing. The "socket" terminus (MIL-T-29504/5) employs a spring and stainless steel, slotted, alignment sleeve to facilitate precisely aligned, physical contact (PC) with the "pin" terminus (/4). The pin terminus is used in the receptacle-half of the connector and the socket is used in the plug-half of the connector. Amphenol-Bendix is the only QPL source for these termini. Table I in Appendix A shows manufacturer ratings for the parts tested.

The test assembly consisted of one connector pair with four contact pairs. The socket termini were housed in the plug-half and the pins were in the receptacle-half. The contacts were terminated to Brand-Rex's OC-1008 Flight Light cable which incorporates a Corning graded index (100/140 m size) radiation hard fiber. On the free ends of each of the eight cable segments was an

Amp "905" SMA connector (compliant with MIL-C-83522).

The transmitter, Honeywell's HFE 4010, was operated in continuous-+ wave mode producing a signal of 850 nm wavelength with approximately 0.16 mW (-7.95 dBm) output power.

Table of Contents



[Next Section](#)



[Up to TVA Homepage](#)



[Back to the Library](#)

Webster: Melanie.Ott@gsfc.nasa.gov



4.0 Test Program

Table 1 shows environmental conditions defined for XTE and TRMM. Table 2 shows the tests used to evaluate the cable assembly and the test equipment employed. Figure 3 shows the testing flow.

Table 1. XTE and TRMM Environmental Conditions:

Temperature	-operating	0C to +5C
	-storage	-20C to +40C
Vibration (Random)	- XTE	7.87 Grms
	- TRMM	14.8 Grms

Table 2. Test Methods and Conditions

Step	Test Equipment	Conditions	
1	Physical Dimensions	Verify dimensions to three significant digits.	
2	Benchmaster oven with Watlow Conditioning controller	85°C for 24 hrs (minimum) followed by -55°C for 24 hrs (minimum)	Tenney Series 942
3	30-G0685 incident light Inspection Nikon Epiphoto inverted Norland Fiber Interferometer,	Inspect the cable for evidence of degradation. Inspect fiber end faces at 200X minimum.	Janavert microscope, microscope,
4	Insertion Loss	See Appendix A	Tektronix

6711 Optical to Electrical		Converter,
Hewlett Packard 54501A		digital
oscilloscope, Noyes OPM1		Optical
Power Meter, DC Power Supply,		Honeywell
HFE4010 transmitter, Hewlett		Packard
8158B Optical Attenuator		
5 Temperature	Test method EIA/TIA-455-3A.	Tenney
Benchmaster oven with Watlow		
Cycling	Using	Series 942
controller with the		
loss set-up.	50 C for max temperature and -20C for minimum temperature, 8 cycles.	insertion
6 Visual	See step 3	See step 3
Inspection		
7 Insertion Loss	See Appendix A	See step 4
8 Random	Test Method MIL-STD-1344,	B335 Shaker
System Lateral Table with		
Vibration 1	Condition V, 18.7 Grms, 6	the
Insertion Loss set-up	minutes in each of three mutually perpendicular directions. Optical throughput shall be measured during exposure using a 0.008mW input signal. A mechanical integrity test will also be performed on the SMA to active device interface. Use bracket A in Figure 9.	
9 Visual	See Step 3	See step 3
Inspection		

10	Insertion Loss	See Appendix A	See step 4
11	Random vibration 1 above Vibration 2	Repeat step 8 using bracket B in Figure 9.	see random
12	Visual Inspection	See Step 3	See step 3
13	Insertion Loss	See Appendix A	See step 4

Figure 3. Testing Flow

Physical Dimensions

Thermal Conditioning

Visual Inspection

Insertion Loss

Temperature Cycling

Visual Inspection

Insertion Loss

Random Vibration (Bracket 1)

Visual Inspection

Insertion Loss

Random Vibration (Bracket 2)

Visual Inspection

Insertion Loss

Table of Contents



[Next Section](#)



[Up to TVA Homepage](#)



[Back to the Library](#)

Webster: Melanie.Ott@gsfc.nasa.gov 

5.0 Test Results and Discussion

5.1 Dimensional Measurements and Interferometer Examinations

The results of the dimensional check showed that the connectors and termini complied with the dimensions and tolerances given by the manufacturer and the associated military specifications (MIL-C-38999 and MIL-T-29504). This leads to the conclusion that the parts being evaluated are physically representative of the parts selected for use on flight hardware.

Interferometer measurements were taken for each of the eight fiber end faces to quantify their initial polish quality (shape). The intent was to create a convex shaped fiber end face centered on the fiber core. Theoretically, optical power loss is reduced with a highly concentric polish which leaves no surface discontinuities in the glass (that will cause reflection) such as cracks, pits and material contamination.

An interferometer image appears as a fringe pattern whose center, or "bull's eye" is at the center of the fiber end face polish radius (Figure 4). This "straight-on" view provides quantifiable polish offset data and can show serious damage to the glass such as crushes and large cracks. The interferometer used in this evaluation also employed a tilt function that showed physical characteristics of the fiber polish from a profile view. Known values such as the fiber size and the distance between the fringes are used to calculate the fiber protrusion (distance between highest point on the glass fiber and the highest point of the ceramic ferrule). Table II in Appendix A shows the data taken for the evaluation cable assembly and the acceptance criteria used by XTE and TRMM.

None of the termini polishes complied with all of the established limits, however they were considered acceptable for the needs of the evaluation. Optical time domain reflectometer (OTDR) measurements performed later in the evaluation (after the first vibration test) confirmed that all four of the fibers were making physical contact. No serious defects were found on any of the eight termini although at least one had significantly large chips in the fiber cladding outer diameter.

Figure 4. Example of an Interferometer Image (Channel 42 pin terminus)




Table of Contents



[Next Section](#)



[Up to TVA Homepage](#)



[Back to the Library](#)

Webster: Melanie.Ott@gsfc.nasa.gov 

5.2 Thermal Conditioning

Two types of thermal conditioning were used prior to vibration testing: a temperature soak and temperature cycling. A high and low temperature soak consisting of a dwell time of 24 hours at each of the temperature extremes, -55°C and 85°C, was used to enhance the stability of the optical cable by driving marginal parts of the assembly to failure. The temperature profile used is shown in Table 3. No failures were found following the soaks however it was observed that the OC-1008 cable stiffened with exposure to high temperature (85°C is the maximum rated temperature due to the material characteristics of the optical fiber coating).

Table 3. Thermal Conditioning Temperature Profile

Transition Time (hours)	Dwell Time (hours)	Temperature °C
Start		25
0.5		85
	24	85
0.75		25
1		-55
	24	-55
0.5		25

5.2.1 Post Thermal Soak Visual Inspection

Following the thermal conditioning, a visual examination of the fiber end faces was performed at 400X, both with and without the use of backlighting. A significant number of features were noted on many of the fiber end faces and were attributed to the original termination process which left surface irregularities. Several of the end faces showed rough edges on the cladding outer diameters and pits in the core and cladding areas. One terminus appeared to have a crack or severe scratch in the fiber cladding. This feature was not seen in the

interferometer photograph and is considered to be an artifact of the original polish, or a condition that might have evolved during thermal conditioning.


At this point in the evaluation, one cable was found broken inside the rear barrel of an SMA connector. This was attributed to insufficient capture of the cable jacket under the barrel that may have caused excessive mechanical strain to the fiber inside the SMA connector. This cable was replaced and subjected to thermal conditioning as described above. An inventory of the features found during the initial visual examination is given in Table III of Appendix A.

5.2.2 Optical Baseline Measurements (Post Thermal Soak Insertion Loss)

Over 380 measurements were taken to baseline the optical throughput for each channel, in each direction, using the sources and equipment that would be used in the vibration test. These measurements were derived from mV values read on a digital oscilloscope (using a optical to electrical converter) and were also taken directly from the display of a hand-held optical power meter (in dBm - dB referenced to mW)2.

The measurement repeatability during these tests was generally between 0 and 0.3 dB, although it varied up to 1.5 dB at times3. The "hands-on" experience showed that measurement repeatability was greatly affected by the compatibility between the threaded coupling mechanisms of the SMA connectors and the link hardware such as the connector adapters on the transceiver and on the optical-to-electrical (O/E) converter. The measurement variability associated with the connector on the O/E converter was insignificant while the connectors on the transceiver caused as much as 1.5 dB variability. The connector often became "locked" in position at some distance from the transmitter (even with the use of the 4 lb torque wrench) and could be re-mated to a position much closer to the transmitter. This aspect of connector loss seemed to be much more significant than the variability attributable to the lack of connector keying (consistent radial position with respect to the transmitter).

Figure 5



The term throughput is used when no launch cable was used in the measurement (units in dBm), as opposed to insertion loss which incorporates a launch cable and is recorded in dB. Some of the lack of repeatability of the data was due to the single fiber SMA connectors used on each of the free ends of the evaluation cable channels. The SMA connector design is non-keyed and incorporates a threaded coupling nut that can cause variation in the mate condition, in air gap width and termini radial alignment, each time the connector is mated.

The baseline insertion loss data is shown in table form in Appendix A. A graph of the insertion loss (using transmitter A, going in the receptacle to plug direction for each of the four channels) is shown in Figure 5. The data shows that the assembly provides a total insertion loss that is within the limits specified for the SMA connectors and M29504 termini combined (< 3.5 dB), for each of the four channels. The very short length of the cable contributes negligible loss to the link.

Table of Contents



[Next Section](#)



[Up to TVA Homepage](#)



[Back to the Library](#)

Webster: Melanie.Ott@gsfc.nasa.gov



5.3 Thermal Cycling Test

A moderately stressful thermal cycling test was run over a four day period to further condition the cable before the vibration test and to screen out infant mortality failures and marginal devices. The optical throughput was monitored every 15 minutes during the cycling, for channel 42 in the receptacle to plug direction. This channel was selected because its large number of mating surface features indicated that it was the most likely to degrade during the test. Six times over the duration of the test, the throughput was measured for each of the three remaining channels.

The test data showed that for channel 42, the optical power transmitted did not decrease by more than 0.2 dB during periods of uninterrupted measurement. Channel 41 and 44 did not show any indication of degradation due to the temperature cycling test. The deltas calculated during and after the test indicate that the throughput remained within the established envelope of variation due to repeatability.

Channel 43 was the only channel that consistently showed increased attenuation during this test. Review of the data taken for this channel throughout the evaluation indicates that the pre-thermal cycling test insertion loss value was abnormally low and was probably due to a better than average mating condition for the SMA connectors. A more repeatable value would have been about 0.5 dB higher. Given this adjustment, the variation for channel 43 was within the repeatability envelope established during baselining. Figure 6 shows initial optical throughput and post-thermal cycling throughput for the four channels. The -7.95 dBm value corresponds to the transmitter output and -11.5 dBm corresponds to the upper limit of the cable assembly's performance rating.

5.3.1 Post Thermal Cycling Visual Inspection

Following thermal cycling, the termini were removed from the "453" connector, examined at 255X to 1000X and photographed. The visual inspection showed a significant number of new surface features in the fiber end faces, mainly on the pin side of the connection. In general, the number and size of rough spots seemed to increase. Some new crescent shaped scratches were found on some termini at the outer edge of the cladding. Table 4 gives a listing of these observations.

The termini were reinserted into the connector halves after the visual examination and it was noted that a significant amount of debris was created due to the degradation of the grommet material by the insertion/removal tool. Later examination of the connector halves also showed

Figure 6




Table 4. Results of Post Thermal Cycling Visual Examination

Terminus	Description of New Features
41R (pin)	Two new rough spots at center Large scratches near radius center and near a rough spot that increased in size
41P (socket)	Several rough spots, no significant change in features present
42R (pin)	Increased number of rough spots Rough spot at crack/scratch site much larger Some lines around large crack/scratch may be micro-cracks, also one near the center.
42P (socket)	Three new large rough spots Pre-existing smaller rough spots grew in size.
43R (pin) outer	Increased number of rough spots especially at cladding diameter (OD) Scratch emanating from cladding OD
43P	No increase in feature number or size

(socket)

44R (pin) Increase in number of rough spots
 Two new scratches, one emanating from new edge chip
 Two large straight scratches may be new

44P
(socket) Some increase in rough spot size
 No significant new features

that the insert material was breaking away and metal filings were being left behind after de-coupling the connectors and after removing the backshells (Figure 7).

Additional examinations were made of the termini mating faces including the use of the scanning electron microscope (SEM) to try to obtain evidence of origins of the rough spots that were not seen when using the optical microscopes. The SEM photographs in Figure 8 show evidence of a rough fiber surface (at 1300X). The three V shaped features can be seen on the optical microscope photograph as rough spots while equally prominent features that can be seen on the SEM photograph cannot be readily identified on the optical microscope image. This indicates that

Figure 7. Metal Filings and Insert Debris on Connector Grommet




Figure 8. SEM Photograph Showing Existing Surface



Roughness Not Seen in Optical Microscope Photograph

the increase in number of rough spots could be that they are simply growing in size due to environmental conditions, including abrasion between the two glass faces during mating, to a size that is discernable by the microscope.

Another possible source of the increased feature size and new scratches could have been from abrasion by glass particles that were liberated from rough areas at the cladding outer diameter. The shapes and locations of the new scratches support this possibility.

The number and size of the features on the pin termini tended to increase while those on the socket half did not. This may be because the pins are more exposed to abrasion during insertion and removal from the connector than the sockets, the socket face being protected by the alignment sleeve.

Table of Contents



[Next Section](#)



[Up to TVA Homepage](#)



[Back to the Library](#)

Webster: Melanie.Ott@gsfc.nasa.gov



5.4 The First Vibration Test - Thick Bracket

A standard test method qualifying high reliability connectors was used to evaluate the connector's vibration performance. This consisted of a set-up that monitored optical throughput during a random vibration profile which provided 18.79 Grms from 20 to 2000 Hz for six minutes in each of three axes (Figure 9, x-axis was the most dynamic for the mounting bracket used). A bracket made of machined aluminum was configured to provide a fixture that was as "quiet" as possible with respect to its own vibration characteristics. The original bracket proposed in the test plan was found to be highly resonant within the test frequency range and so was not used to establish the qualification data. It was used in a subsequent vibration test described below as supplemental testing. Both brackets are shown in Figure 10.

Figure 9. Random Vibration Profile for First Test (X-Axis)






Figure 10. Brackets Used for First and Second Vibration Tests




Bracket A - Used for the First Vibration Test



Bracket B - Used for the Second Vibration Test

Figure 11. Vibration Test Set-Up



The optical signal was reduced to 8W (-20.969 dBm), using an optical attenuator, to simulate a signal similar in amplitude to that expected for the actual MIL-STD-1773 application. Optical monitoring was accomplished through the use of optical to electrical converters and a Hewlett Packard 54501A digital oscilloscope driven by external software. Two optical channels were monitored

during each test run. To get data for all four channels in the x-direction, the x-axis test was run twice, once monitoring channels 41 and 42 and then monitoring channels 43 and 44. A Tektronics TDS 544 digital oscilloscope was used to view the signal real-time and operated in storage mode to save throughput deviations (in mV) over the duration of the test run.

The software monitored the oscilloscope, changing from one channel to the other every five seconds. A trigger was set at a mV level equal to a 0.45 dB reduction in optical signal. When a trigger event occurred, the program would capture the Vmin value from the oscilloscope, tag it with the corresponding channel number and dump it to a data file. It would then switch to the other channel and wait for a similar trigger event. If no event occurred, the program would switch to the next channel after five seconds. At the end of every test, a false trigger event was simulated on each of the channels to verify that the program and scope were still working as intended. The vibration test set-up is shown in Figure 11.

The tests were run in an order which minimized the effects of re-mating the SMA connectors. After the connector was mounted to the bracket, it was torque striped at every coupling ring on the connector and backshell. Inspection after the test did not show any break in the torque striping or other evidence of backing-off on any of the coupling mechanisms.

The data taken for this test is given in appendix A. The only trigger events that occurred during testing using the thick bracket were on channel 41 during the first x-axis exposure. Figure 12 shows the optical throughput before the X1 test for channel 41PR, the approximate throughput values at the time of the trigger events and the throughput measured for the channel at the end of the 6 minute test. This data shows that the channel fully recovered after the trigger events while increasing in loss by as much as 1.2 dB during the events. The lack of trigger events for the rest of the five remaining axis runs and the lack of contamination on channel 41 pin and socket suggests that channel 41 physically settled into a stable alignment position due to the application of vibration and that the discontinuities observed in Figure 12 do not necessarily indicate part failure.

Figure 13 shows that after each of the six vibration tests, there were no significant decreases in optical throughput. The data is plotted, pre-test value with post-test value, in the order the channels were tested. Again, to reduce SMA repeatability effects, measurements were not taken for each channel after each axis run, but

only for those runs for which they were actively monitored.

Figure 12





Figure 13



The second part of the vibration test was designed to determine whether the SMA connector ferrules would crush the active device lenses during vibration. The test results showed that the SMA connector ferrules did not affect the active device lenses and that no significant change occurred in throughput for the test cable. Figures 14 and 15 show that one of the two active devices subjected to the mated condition, did exhibit evidence of scratches on the metal package, but not on the glass.

Figure 14. Transmitter B Before Vibration Test




Figure 15. Transmitter B After Vibration Test




Table of Contents



[Next Section](#)



[Up to TVA Homepage](#)



[Back to the Library](#)

Webster: Melanie.Ott@gsfc.nasa.gov



5.4.1 Visual Examination Following the First Vibration Test

Following the vibration test using the thick bracket, the termini were removed and photographed before and after cleaning. Table 5 summarizes the observations following the first vibration test.

The size and shape of the metal filings found on 42P (Figure 16) suggest alignment sleeve fretting. This fretting occurs when the terminus revolves at some minute angle, around its longitudinal axis (without rotation) abrading the inside of the alignment sleeve. It should be noted that the alignment sleeve for channel 42 was noticeably looser than the others and often stayed inside of the connector when the termini was extracted. Figure 17 compares the condition of the ferrule of the pin for channel 42 and the pin for channel 41. The scratches seen on the channel 42 pin may be indicative of that circular motion inside of the alignment sleeve during vibration. Channel 41 pin does not show these scratches. The slot width of channel 42's alignment sleeve measured approximately 19% larger than the slot on the channel 41 alignment sleeve indicating that there may have been less of a retaining force between the sleeve and the channel 42 ferrules allowing ferrule movement.

The metal contamination found on 43R and 44P were similar to that seen on the rubber grommet due to abrasion between the connector and backshell and are large enough to block the optical path.

Table 5. Visual Observations Following the First Vibration Test

Terminus Found	Contamination Noted After Cleaning	Cleaning	New Features
41P	drops in a circular pattern (water vapor)		none
41R	none in appearance to cladding outer contamination or a located at one end of		- scratch similar existing scratches - feature at diameter may be rough spot, the new scratch
42P	large amount of metal filings of rough areas in the sizes ranging between approximately many very small		two or more new fiber core and

200 m x 4 m to specks less than 1 m square. rough spots

42R large amount of small **metal pieces** in the range of 4 m square, most much smaller two new scratches

43P several drops (water vapor) none

43R - large **metal pieces** found on the spot at cladding
ceramic ferrule (50 m x 100 m) on with small scratch
fiber core.
- a few drops (water vapor)
scratches, one deep


- one new rough outer diameter emanating from it
- two large

44P - one large **metal piece** on ferrule in cladding
(20 m square)
- drops in circular pattern (water vapor)

one new rough spot
outer diameter

44R pre-existing alcohol residue none


Figure 16. Pre- and Post Vibration Visual Examination (255X) 42P



Pre-Vibration

Post-Vibration

Figure 17. Ceramic Ferrules of 42R and 41R After Vibration Testing



Following the visual examination, the termini shrink tubing was re-worked. The original shrink tubing had lost its ability to adequately support many of the termini. This degradation was due to the large number of times the termini had been inserted and removed. Following reinsertion of the termini into the connector, an optical time domain reflectometer measurement was taken for each channel. The results showed that all four were making physical contact when the connector was fully mated. A small reflection was found approximately 8 inches from the end of the SMA connector on the plug side of channel 44.

[Table of Contents](#)



[Next Section](#)



[Up to TVA Homepage](#)




[Back to the Library](#)

Webster: Melanie.Ott@gsfc.nasa.gov 

5.4.2 Optical Measurements Following the First Vibration Test (Vibration 1)

Insertion loss for the evaluation cable is shown in Figure 18 which compares the baseline value with the value recorded after the termini were reinserted into the connector, following post-vibration visual examinations and shrink tubing rework. This data represents the combined effects of repeated termini insertion and removal, handling, SMA non-repeatability and exposure to the temperature and vibration environments on channel loss stability. The large change in loss shown for channel 41, which was not seen immediately following the vibration test, indicates that the environmental exposures probably had less affect on the channel loss than the other factors noted above.

Figure 18



Although channels 42 through 44 showed a change in insertion loss between 0.1 and 0.8 dB, they stayed well below the manufacturer's ratings of 3.5 dB maximum. A review of the data indicates that the insertion loss for channels 43 and 44 increased after thermal cycling by about 0.2 dB which may correspond to the overall increase in surface features noted at that time. The factors noted above such as repeatability, handling and changes in radial alignment between the terminus pairs may account for an additional portion of the 0.8 dB increase in insertion loss. It is interesting to note that even though the fiber end faces for both the pin and socket for channel 42 saw significant increase in surface features over the duration of the test, channel 42's optical

data was the most stable throughout the testing.

Table of Contents



[Next Section](#)



[Up to TVA Homepage](#)




[Back to the Library](#)

Webster: Melanie.Ott@gsfc.nasa.gov A small yellow sun-like icon with rays.

5.5 Supplemental Testing: The Second Vibration Test Using the Thin Bracket

The second vibration test was run to see if any catastrophic failures would occur due to a less than stable mounting bracket. It was run in exactly the same way as the first test except that the original bracket, described in the test plan (Figure 10), was used. Figure 19 shows the vibration profile extended to the bracket when using the same test conditions as those used in the first vibration test. The resonant peaks and resulting increase in total force extended to the connector resulted from the physical design of the bracket; namely the thin sides, the height and the lack of side support. The total force of this test was 37.66 Grms.


Figure 19. Vibration Profile for the Thin Bracket



No trigger events were found during the first five runs (X1, X2, Y1, Y2, Z1). During the last z-axis test (Z2), several trigger events (momentary loss in excess of 0.5 dB) occurred for channel 43 during the first minute of the six minute test. Data for the second vibration test is provided in appendix A. No backing-off from the connector or backshell was noted and there was no disruption to the torque striping.

Figure 20 compares optical power throughput measurements taken before and after the second vibration test (-11.5 dBm represents the maximum loss rating and -7.95 dBm the launch power). Channel 43 experienced the most degradation (1.2 dB) due to the second vibration test. Figure 20 data was taken before the termini were visually examined and cleaned.

Figure 20



5.5.1 Visual Examination Following the Second Vibration Test

After the second vibration test, the termini were removed and photographed at 255X magnification before and after cleaning. Table 6 lists the results of visual observations including contamination found before the termini were cleaned compared to the post Vibration (1) photographs.

Although some contamination was observed on most of the fiber end faces, the amount and particle sizes were significantly smaller than noted after the first vibration test. With the exception of the rough spots noted on the channel 42 pin and socket, no new features evolved. No large contamination or defect was found on either the pin or socket of channel 43 that could explain the trigger events noted during the last vibration run or the increase in loss (1.2 dB) measured after the test.

Table 6. Visual Observations Following the Second Vibration Test

Terminus	Contamination Noted Before Cleaning	New Features Found After Cleaning
41P	none	none
41R scratches	residue smear (material unknown)	four large
42P	very small amount of particulate	large

rough area at cladding/core (half the total core size)	contamination (may be metal)	interface
42R rough area at cladding/core (half the total core)	large amount of small metal particles in the range of 4 m square, most much smaller	large interface size)
43P	very small particles (may be metal)	none
43R	residue smear (material unknown)	none
44P	small amount of smear material	none
44R	very small particles (may be metal)	none

The rough spots described for the channel 42 fiber end faces are interesting in that they are very different than the dark rough spots noted on the end faces throughout the evaluation and are much larger. They do not appear to have depth like all of the other rough spot features but possess the texture of small cracks or scratches. More analysis is required to identify the exact nature and cause of all the rough spots, scratches and other unidentifiable features.

Table of Contents



[Next Section](#)



[Up to TVA Homepage](#)



[Back to the Library](#)

Webster: Melanie.Ott@gsfc.nasa.gov

6.0 Conclusions

The evaluation showed that this fiber optic connector system, when subjected to 18 Grms of random vibration, will not suffer a catastrophic failure. It should be noted that a substantial amount of metal contamination evolved on the termini which had the loosest alignment sleeve. Similar contamination was not found on the three remaining termini pairs. This suggests that there should be a limit set for the "insertion force" or "retention force" of the alignment sleeve with each of the mating termini. A measurement of the retention force of the alignment sleeves on the three unaffected termini pairs would give an indication of an acceptable value.

Another source of large sized contamination seemed to be the backshell where debris freely moved to the mating area during termini insertion or due to handling. This contamination debris- metal flakes and ground pieces of grommet and insert material - must be removed. Attempts to remove the visible material (on the outer surfaces of the connector) were not very successful. This indicates that some type of cleaning procedure should be developed for use with these connectors (when using optical termini), especially after the termini have been inserted. Improvement of the insertion and removal mechanisms, the tools, internal retention mechanism or termini clearance space inside the connector, would likely reduce the occurrence of the organic debris.

The termini with the most rough cladding outer diameter seemed to degrade the most significantly with respect to surface scratches and the number and size of rough spots.. The terminus side not protected by the alignment sleeve during insertion into the connector, tended to show a greater increase in surface features though some of the termini pairs (both halves) did not change at all. This suggests that polishes (or coating removal) which leave rough edges will most likely degrade with handling.

Although surface defects in the glass fiber should be avoided for long term reliability, the results of this evaluation did not link their presence with short term degradation in optical performance. The mild thermal preconditioning enabled at least one defect to grow into a crack. More rigorous conditioning performed on the cables may produce more cracks.

Both vibration tests showed that this connector system is capable of withstanding as much as 37 Grms without failing. The change in optical loss ranged between none and 1dB (generally the specification limit).

Table of Contents



[Next Section](#)



[Up to TVA Homepage](#)



[Back to the Library](#)

Webster: Melanie.Ott@gsfc.nasa.gov 

7.0 Recommendations

It is recommended that this part, the "453" connector and M29504 termini, should continue to be listed in the GSFC PPL for use in applications where the thermal excursions are generally mild with respect to the temperature rating of the optical cable. This connector system should be adequate for vibration environment below 37 Grms, provided the alignment sleeves meet a minimum retention force with the termini ferrules. This force should be quantified. It is important to understand how the connector will be mounted and any additional force that will be extended to the connector during vibration as a result of the mounting configuration.

It is extremely important to understand sources of contamination that may interfere with the light path and physical mate of the termini. Contamination that is sufficiently large or sufficiently prevalent can cause temporary signal loss. Therefore, adequate cleaning techniques must be used to remove the contaminating material from the connector. This is difficult given the configuration of the socket contacts in particular. Further, the materials on the rear of the connector (resilient grommet and epoxy) seem to retain particulate contamination, such as metal shavings, which makes it difficult to keep the connector clean.

The goal with PC polish is to provide a fiber end that is convex and as free as possible of surface discontinuities. The termini pairs tested here had a range of polish qualities from good to poor, though none showed a degradation in optical performance that could be directly associated with the fiber end face surface. Some of the photographs suggest that large cladding edge chips can grow in size with multiple matings and thereby free glass particles that can pit or scratch the glass surface. A reliability analysis should be performed to better quantify the relationship between the types and characteristics of the surface features observed here and the long term connector optical performance. A life test utilizing thermal and tensile stress on the cable could be used in an attempt to determine time to failure for termini with significant defects.

The connector insert and grommet was significantly degraded during this evaluation. This degradation may be due to a combination of terminus insert/removal cycling, the build up of epoxy and shrink tubing on the terminus (preventing proper operation of the removal tool) or an ineffective insert/removal tool. Although the degradation of the grommet and insert did not seem to affect

the optical performance of the connector, it did contribute greatly to the contamination situation. All efforts should be made to greatly reduce the insert/removal cycles when using optical termini in this connector and to be aware of the limitations this problem extends to the termination process (choice of materials and other limitations on the amount of material used at the termini rear barrel).

Table of Contents



[Next Section](#)



[Up to TVA Homepage](#)



[Back to the Library](#)

Webster: Melanie.Ott@gsfc.nasa.gov



8.0 Acknowledgments

The following organizations and individuals were instrumental to the success and completion of this evaluation and are recognized for their support and contribution:

The XTE and TRMM projects, Roger Miller, 733.1; Rob Galleher, Jackson & Tull, 733;

Keith Kienzle and Vernon McCarter, Jackson & Tull, 733; Nancy Stafford, 750.2; Alex Coleman, 733.1; John Kolasinski, 733.2; Mike Delmont, 303; Mark Walter, J&T, 733; the NSI Vibration Laboratory Team including Darrel Merrill and Walt Plesnick, 750.5; Onur Atabek, 750; Bob Savage, 312; Richard Nace, 312; Mike Fisher, Unisys, 300.1; George Berthold, Unisys, 300.1; and Rodney Farmer, 300.1, Dr. Kusum Sahu, 300.1.

Table of Contents



[Next Section](#)



[Up to TVA Homepage](#)



[Back to the Library](#)

Webster: Melanie.Ott@gsfc.nasa.gov A small graphic element consisting of a yellow sun-like icon with rays, positioned next to the email address.

Appendix A

Table I. Part Ratings.	<u>A1</u>
Test Method for Insertion Loss/Optical Throughput.	<u>A2</u>
Table II. Interferometer Measurement Results.	<u>A3</u>
Table III Initial Visual 400X.	<u>A4</u>
Table IV. Baseline Insertion Loss and Optical Throughput Data	<u>A5</u>
Table V. Data for First Vibration Test - Thick Bracket.	<u>A6</u>
Table VI. Data for Second Vibration Test - Thin Bracket.	<u>A7</u>

Table of Contents



[Up to TVA Homepage](#)



[Back to the Library](#)

Webster: Melanie.Ott@gsfc.nasa.gov

TABLE I. Part Ratings

Part Type Coupling	Part Number	Operating Temp Range (C)	Insertion Loss at 850 nm	Change in IL due to low temp (or temp cycle)	Vibration Level	Minimum Bend Radius
Torque (in-lb)						
SMA Connector 4	Amp FSMA 905	-65 to +85	1.49	-	20 Gs	-
Termini -	M29504/04-4050 (and -4044)	-65 to +150	2.0	mechanical criteria only	15 Gs	-
Multi-Termini 16 Connector	Amphenol Bendix/TVS06RF- 13-4P(453) and receptacle half	-65 to +200	1.5	-	60 Gs	-
Backshell - w/Strain Relief saddle clamp:	620HS011M13	-65 to 200	-	-	60 Gs	-
auxiliary grommet: -	377HS025M136G-186 (3") and 377HS025M134G-186 (2")				sine, 41 Gs random	
Cable - 1008	Brand-Rex/OC-	-55 to +85	10 dB/km	-	-	2 in
Epoxy - BIPAX	Tra-Con BA-F253	-60 to +175	-	-	-	-
Shrink Tubing - Mylar (Alpha Wire Corp)	FIT-130-1/8		-	-	-	-

Table of Contents



[Index of Appendix A](#)



[Up to TVA Homepage](#)



[Back to the Library](#)

Webster: Melanie.Ott@gsfc.nasa.gov A small yellow sun icon with rays.

Test Method for Insertion Loss/Optical Throughput:

Remove all equipment dust caps and dry wipe lenses (very gently). Dry wipe all connector terminations at least once before making measurements. Verify unusual measurements by re-wiping terminations and lenses. Dry wipe all dust caps before replacing them on the connectors or optical equipment.

Each segment of the launch cables should be measured independently and then concatenated as it will be used during the vibration test. To determine the throughput, attach the cable, or link, of interest as shown below - between emitter source A (or B) and the O/E converter. The oscilloscope data is given in mV. Convert to dBm by dividing by 5, taking the log10 and multiplying by 10. Control measurements should be taken at the beginning of each measurement session using the D80-D90 control cable, the SMA-ST adapter cables (used on attenuator) and the evaluation channels without launch cables. A control measurement should also be taken for each evaluation channel by using the SMA-ST adapter cables as launch cables. Data should be taken with the attenuator set to zero. The attenuation setting should then be recorded for a 0.008mW throughput.




Table of Contents



Index of Appendix A



[Up to TVA Homepage](#)



[Back to the Library](#)

Webster: Melanie.Ott@gsfc.nasa.gov ☼

Table II. Interferometer Measurement Results

Protrusion (microns)	offset (microns)		Radius of Curvature (mm)	(microns)
-	Requirement minimum		10	> 0
35	Requirement maximum		20	0.2
Terminus Type	Serial Number	Connector Half		
socket 14	41	Plug	5.3	0.3
pin 40.8	41	Receptacle	9.3	0.08
socket 28	42	Plug	6.86	0.27
pin 18.2	42*	Receptacle	6.45	0.25
socket 35	43	Plug	4.1	0.27
pin	43	Receptacle	4.4	0.3

33.6

socket 28	44	Plug	8.2	0.08
pin 8	44	Receptacle	16.5	0

* Data taken for hand polished terminus. See visual examination results in Appendix A.

Table of Contents



[Index of Appendix A](#)



[Up to TVA Homepage](#)



[Back to the Library](#)

Webster: Melanie.Ott@gsfc.nasa.gov ☼

Table III Initial Visual 400X

Features							
notes taken during visual exam				2			
Type	SN	Conn	chip in Half OD 1	rough spots in cladding	rough spots in cladding	scratches	deep scratch or cracks
SMA	41	Plug	very small chip in OD 1:30, rough spot at small	1 med	-	-	-
9:45							
socket	41	Plug	2 - trail of seven rough spots across center 2:30 to 8:30, one in cladding	1 med, a large few small	7 med, many small	-	-
10:30,			two at OD 5:30 and 8:00, @40				
smaller rough spots							
pin	41	Recpt	rough large rough spot at 6:30, med ones at 9:30, 11:30, 12:30, center 3:30, 5:30, polishing scratch center 5:30 to OD 10:00, >100 small rough spots	1 large, 3 edge numerous numerous small	2 medium, med, numerous small	one	-
SMA	41	Recpt	- polishing scratches, one deep at 7:30	-	-	several, 1 deep	-
SMA	42	Plug	- two very small nicks at 2:00 & 4:45, Med rough spots at 2:00, 9:30, light polishing scratches, dark spot at 10:00 is dirt	2 med	-	several light	-

socket 42 Plug rough 1 med 1 large several
large pit at 1:00 center, rough spots edge light
at OD, 11:00 - 2:30, large rough area
at 11:00, small rough spot at edge of
polishing scratch at 300, > 50 small
rough spots

pin 42 Recpt 2 large 2 med, 1 1 med, 3 several 1 large
crack or deep scratch from 12-900,
at crack/ at crack/
hand polish scratches, 3 rough spots
scratch scratch
at middle of crack, scratch (or crack)
site site, many
through center w/rough spots at
small
center, med rough spots at 12:00,
2:30, 3:30, 6:00, 9:00, chip in OD at
3:00 & 8:45, >60 small rough spots

SMA 42 Recpt - - - 1 small -
smooth OD, many polishing scratches

SMA 43 Plug - 1 - 2 light -
no anomalies (dark spot is dirt),
light polishing scratches

socket 43 Plug some 16 med, 4 med several,
some OD roughness, pits at 1:00, several light
6:15, 6:45, 8:15, 8:30, 9:15, 10:00,
small
11:00, 11:15, 12:00, >35 small rough
spots, light polishing scratches

pin 43 Recpt very many 1 large, 3 1 (may -
heavy pitting at OD edge, large rough

rough associated med, very be a
spot at center 12:00, med rough spots with edge few small crack)
at 1:00, 6:00, 6:30, scratch (or chips
crack) at 4:30, @10 small rough spots

SMA 43 Recpt - 1 - several, -
smooth OD, several light polishing
scratches

SMA 44 Plug - - several, -
no anomalous features noted light

socket 44 Plug some 1 med, several, -
large chips in OD 8:45, 10:00, med roughness several light
rough spots at 9:15 in core, > 50 2 chips small
small rough spots in core

pin 44 Recpt rough, 1 large, - several, -
large rough spots at 8:00, rough OD 3 chip very few light
w/chips at 3:00, 5:30, 7:45, 9:00, areas small
light polishing scratches, 3 small
rough spots

SMA 44 Recpt - - - - -
no anomalous features noted

SMA M 1 some several some light -
@ 10 small rough spots (short) small small

SMA M 2 some several - light
@ 10 small rough spots (short) small

1 OD: Outer Diameter

2 Numbers represent radial position of the anomaly (clock position).

Table of Contents



[Index of Appendix A](#)



[Up to TVA Homepage](#)



[Back to the Library](#)

Webster: Melanie.Ott@gsfc.nasa.gov



Table IV. Baseline Insertion Loss and Optical Throughput Data

Transmitter Launch Cable Cable	Evaluation Cable Section	Throughput in dBm	Insertion Loss of Evaluation Cable Section (dB)*	Eval
Section/Source				
A	11/9-10/12	none	-9.84	
A 41PR/A	11/9-10/12	41 Plug to Receptacle	-10.83	0.99
A	none	41 Plug to Receptacle	-7.76	
A 41RP/A	11/9-10/12	41 Receptacle to Plug	-11.64	1.80
A	none	41 Receptacle to Plug	-8.86	
B	11/9-10/12	none	-9.72	
B 41PR/B	11/9-10/12	41 Plug to Receptacle	-9.51	-0.21
B	none	41 Plug to Receptacle	-8.70	
B 41RP/B	11/9-10/12	41 Receptacle to Plug	-11.20	1.49
B	none	41 Receptacle to Plug	-8.66	

Baseline Insertion Loss and Optical Throughput Data

A	11/9-10/12	none	-9.84	
A 42PR/A	11/9-10/12	42 Plug to Receptacle	-11.60	1.76
A	none	42 Plug to Receptacle	-8.29	
A 42RP/A	11/9-10/12	42 Receptacle to Plug	-11.60	1.80
A	none	42 Receptacle to Plug	-8.57	
B	11/9-10/12	none	-9.72	
B 42PR/B	11/9-10/12	42 Plug to Receptacle	-11.10	1.42
B	none	42 Plug to Receptacle	-8.86	
B 42RP/B	11/9-10/12	42 Receptacle to Plug	-11.20	1.44
B	none	42 Receptacle to Plug	-8.87	
A	11/9-10/12	none	-9.84	
A 43PR/A	11/9-10/12	43 Plug to Receptacle	-11.46	1.62
A	none	43 Plug to	-8.63	

Baseline Insertion Loss and Optical Throughput Data

Receptacle

A 43RP/A	11/9-10/12	43 Receptacle to Plug	-11.34	1.50
A	none	43 Receptacle to Plug	-8.42	
B	11/9-10/12	none	-9.72	
B 43PR/B	11/9-10/12	43 Plug to Receptacle	-11.05	1.33
B	none	43 Plug to Receptacle	-8.42	
B 43RP/B	11/9-10/12	43 Receptacle to Plug	-11.01	1.29
B	none	43 Receptacle to Plug	-8.89	
A	11/9-10/12	none	-9.84	
A 44PR/A	11/9-10/12	44 Plug to Receptacle	-11.20	1.32
A	none	44 Plug to Receptacle	-7.92	
A 44RP/A	11/9-10/12	44 Receptacle to Plug	-11.20	1.39
A	none	44 Receptacle to Plug	-7.65	

Baseline Insertion Loss and Optical Throughput Data

B	11/9-10/12	none	-9.84	
B 44PR/B	11/9-10/12	44 Plug to Receptacle	-10.90	1.23
B	none	44 Plug to Receptacle	-8.56	
B 44RP/B	11/9-10/12	44 Receptacle to Plug	-10.90	1.23
B	none	44 Receptacle to Plug	-8.52	

* Eval Cable Section Insertion Loss = Loss for the SMA connector pair + loss for the given "453"-M29504 pair. Table V. Data for First Vibration Test - Thick Bracket

Table of Contents



[Index of Appendix A](#)



[Up to TVA Homepage](#)



[Back to the Library](#)

Webster: Melanie.Ott@gsfc.nasa.gov 

Table V. Data for First Vibration Test -Thick Bracket

Table V. Data for First Vibration Test - Thick Bracket

Monitor Scope		Tektronix Storage Scope						HP	
Data	Date	XTMR	cable	attenuator	attenuator	cable	cable	O/E	Vmin
dBm	Vmax	Hi	Lo	Pk-Pk	Mean setting				(V)
(min)	(V)	(V)	(V)	(V)	(V)				
Pre-X1 -9.881	013095 0.515	A	UnLbld	1344130	0	Lbld	-	B010279	0.514
Pre-X1 11.707	013095 0.342	A	UnLbld	1344130	0	Lbld	41P/R	B010279	0.336
Pre-X1 21.178	013095 0.041	A	UnLbld	1344130 0.0084	9.33	Lbld	41P/R	B010279	0.038
Post-X 21.124	013095 0.041	A	UnLbld	1344130 0.0438 0.0358	9.33 0.008 0.04006	Lbld	41P/R	B010279	0.039
Post-Y -	013095 0.04243	A	UnLbld	1344130 0.0438 0.0362	9.33 0.0076 0.0398	Lbld	41P/R	B010279	0.039
Pre-Y2 -	013095 0.0414	A	UnLbld	1344130	9.33	Lbld	41P/R	B010279	0.038
Pre-X2 21.160	013195 0.042	A	UnLbld	1344130	9.33	Lbld	41P/R	B010279	0.038
Pre-Z2 10.658	013195 0.436	A	UnLbld	1344130	0	Lbld	41P/R	B010279	0.430
Pre-Z2 21.178	013195 0.041	A	UnLbld	1344130 0.0434 0.0354	10.39 0.008 0.0393	Lbld	41P/R	B010279	0.038
Post-Z 21.178	013195 0.041	A	UnLbld	1344130 0.0426 0.035	10.39 0.0076 0.03892	Lbld	41P/R	B010279	0.038
Pre-X1 9.802	013095 0.527	B	11/9	1340113	0	10/12	-	B010278	0.523
Pre-X1 11.286	013095 0.376	B	11/9	1340113	0	10/12	42P/R	B010278	0.372
Pre-X1 21.160	013095 0.041	B	11/9	1340113 0.0104	9.79	10/12	42P/R	B010278	0.038
Post-X 21.178	013095 0.042	B	11/9	1340113 0.0432 0.0356	9.79 0.0076 0.0390	10/12	42P/R	B010278	0.038
Post-Y 21.160	013095 0.041	B	11/9	1340113 0.0436 0.036	9.79 0.0076 0.0397	10/12	42P/R	B010278	0.038
Pre-Y2 21.020	013195 0.042	B	11/9	1340113	9.79	10/12	42P/R	B010278	0.040
Pre-Z2 11.568	013195 0.352	B	11/9	1340113	0	10/12	42P/R	B010278	0.349
Pre-Z2 21.125	013195 0.041	B	11/9	1340113 0.0432 0.0348	9.48 0.0084 0.0388	10/12	42P/R	B010278	0.039
Post-Z 21.125	013195 0.041	B	11/9	1340113 0.0428 0.0352	9.48 0.0076 0.0387	10/12	42P/R	B010278	0.039
Pre-Y2 -9.863	013195 0.521	A	UnLbld	1344130	0	Lbld	-	B010279	0.516

Table V. Data for First Vibration Test -Thick Bracket

Pre-Y2	013195	A	UnLbld	1344130	0	Lbld	43R/P	B010279	0.387
11.108	0.392								
Pre-Y2	013195	A	UnLbld	1344130	9.98	Lbld	43R/P	B010279	0.038
21.178	0.041	0.0434	0.0354	0.008	0.03916				
Post-Y2	013195	A	UnLbld	1344130	9.98	Lbld	43R/P	B010279	0.038
21.178	0.041	0.0426	0.0354	0.0072	0.03898				
Pre-X2	013195	A	UnLbld	1344130	9.98	Lbld	43R/P	B010279	
21.238	0.0426	0.0356	0.0076	0.03816					
Post-X2	013195	A	UnLbld	1344130	9.98	Lbld	43R/P	B010279	
21.308	0.0426	0.035	0.0076	0.03882					
Pre-Z1	013195	A	UnLbld	1344130	0	Lbld	-	B010279	0.564
-9.477	0.569								
Pre-Z1	013195	A	UnLbld	1344130	0	Lbld	43R/P	B010279	0.433
10.626	0.439								
Pre-Z1	013195	A	UnLbld	1344130	10.41	Lbld	43R/P	B010279	0.039
21.125	0.041	0.043	0.0354	0.0076	0.03924				
Post-Z1	013195	A	UnLbld	1344130	10.41	Lbld	43R/P	B010279	0.036
21.125	0.042	0.0434	0.036	0.0072	0.03964				
Pre-Y2	013195	B	11/9	1340113	0	10/12	-	B010278	0.511
-9.907	0.515								
Pre-Y2	013195	B	11/9	1340113	0	10/12	44R/P	B010278	0.375
11.250	0.378								
Pre-Y2	013195	B	11/9	1340113	9.8	10/12	44R/P	B010278	0.038
21.178	0.041	0.044	0.0356	0.0084	0.03948				
Post-Y2	013195	B	11/9	1340113	9.8	10/12	44R/P	B010278	0.037
21.125	0.041	0.0444	0.0364	0.0084	0.03974				
Pre-X2	013195	B	11/9	1340113	9.8	10/12	44R/P	B010278	
21.238	0.0428	0.0356	0.0072	0.03954					
Post-X2	013195	B	11/9	1340113	9.8	10/12	44R/P	B010278	
21.192	0.0432	0.036	0.0072	0.03964					
Pre-Z1	013195	B	11/9	1340113	0	10/12	-	B010278	0.524
-9.801	0.527								
Pre-Z1	013195	B	11/9	1340113	0	10/12	44R/P	B010278	0.350
11.550	0.532								
Pre-Z1	013195	B	11/9	1340113	9.47	10/12	44R/P	B010278	0.039
21.072	0.041	0.0432	0.0348	0.0084	0.0396				
Post-Z1	013195	B	11/9	1340113	9.47	10/12	44R/P	B010278	0.039
21.125	0.041	0.0428	0.0344	0.0084	0.03866				

Table of Contents[Index of Appendix A](#)[Up to TVA Homepage](#)[Back to the Library](#)

Table V. Data for First Vibration Test -Thick Bracket

Webster: Melanie.Ott@gsfc.nasa.gov 

Table VI. Data for Second Vibration Test - Thin Bracket

HP Monitor Scope Data				Tektronix Storage Scope Data							
Vmax	Date	XTMR	cable	attenuat	attenuat	cable	cable	O/E	Vmin	dBm	
(min)	Hi	Lo	Mean	Pk-Pk	or	or settin	g		(V)		
Baseline -10.013	022895	A	Unlbl	1344130	0	lab	-	10279	0.499	-9.734	
Baseline -19.747	022895	A	Unlbl	1344130	9.8	lab	-	10279	0.053		
Baseline -9.662	030195	A	Unlbl	1344130	0	lab	-	10279	0.541	-9.694	
Baseline -19.355	030195	A	Unlbl	1344130	9.8	lab	-	10279	0.058		
Baseline -9.718	030195	A	Unlbl	1344130	0	lab	-	10279	0.534	-9.751	
Baseline -19.469	030195	A	Unlbl	1344130	9.8	lab	-	10279	0.057		
Baseline -9.809	030295	A	Unlbl	1344130	0	lab	-	10279	0.523	-9.699	
Baseline -19.508	030295	A	Unlbl	1344130	9.8	lab	-	10279	0.056		
Baseline -9.792	022895	B	11/9	1340113	0	10/12	-	10278	0.525	-9.755	
Baseline -19.547	022895	B	11/9	1340113	9.8	10/12	-	10278	0.056		
Baseline -10.545	030195	B	11/9	1340113	0	10/12	-	10278	0.441	-9.677	
Baseline -20.223	030195	B	11/9	1340113	9.8	10/12	-	10278	0.048		
Baseline -9.825	030195	B	11/9	1340113	0	10/12	-	10278	0.521	-9.761	
Baseline	030195	B	11/9	1340113	9.8	10/12	-	10278	0.055		

Data for Second Vibration Test

-19.586											
Baseline	030295	B	11/9	1340113	0	10/12	-	10278	0.529		
-9.759	-9.712										
Baseline	030295	B	11/9	1340113	9.8	10/12	-	10278	0.057		
-19.469											
Pre-x1	022895	A	Unlbl	1344130	0	lab	41RP	10279	0.399		
-10.985											
Pre-x1	022895	A	Unlbl	1344130	9.66	lab	41RP	10279	0.040		
-21.020	0.043	0.044	0.036 0.040	0.008							
Post-x1	022895	A	Unlbl	1344130	9.66	lab	41RP	10279	0.043		
-20.674	0.046	0.048	0.040 0.044	0.008							
Pre-y2	030195	A	Unlbl	1344130	0	lab	41RP	10279	0.135		
-15.702											
Pre-y2	030195	A	Unlbl	1344130	6.07	lab	41RP	10279	0.039		
-21.072	0.043	0.044	0.036 0.040	0.009							
Post-y2	030195	A	Unlbl	1344130	6.07	lab	41RP	10279	0.040		
-20.984	0.042	0.043	0.036 0.040	0.007							
Pre-z1	030195	A	Unlbl	1344130	0	lab	41RP	10279	0.166		
-14.802											
Pre-z1	030195	A	Unlbl	1344130	6.16	lab	41RP	10279	0.039		
-21.072	0.043	0.046	0.036 0.042	0.010							
Post-z1	030195	A	Unlbl	1344130	6.16	lab	41RP	10279	0.041		
-20.819	0.046	0.048	0.040 0.044	0.008							
Pre-x1	022895	B	11/9	1340113	0	10/12	42RP	10278	0.165		
-14.828											
Pre-x1	022895	B	11/9	1340113	6.02	10/12	42RP	10278	0.040		
-21.020	0.043	0.044	0.036 0.040	0.008							
Post-x1	022895	B	11/9	1340113	6.02	10/12	42RP	10278	0.040		
-21.020	0.043	0.045	0.036 0.041	0.009							
Pre-y2	030195	B	11/9	1340113	0	10/12	42RP	10278	0.324		
-11.891											
Pre-y2	030195	B	11/9	1340113	9.58	10/12	42RP	10278	0.041		
-20.919	0.041	0.044	0.036 0.039	0.0088							
Post-y2	030195	B	11/9	1340113	9.58	10/12	42RP	10278	0.041		
-20.833	0.041	0.044	0.035 0.040	0.008							

Data for Second Vibration Test

Pre-z1 -11.537	030195	B	11/9	1340113	0	10/12	42RP	10278	0.351
Pre-z1 -21.072	0.042	0.043	11/9 0.035	1340113 0.039	9.5	10/12	42RP	10278	0.039
Post-z1 -21.160	0.043	0.043	11/9 0.035	1340113 0.039	9.5	10/12	42RP	10278	0.038
Pre-x2 -12.168	022895	A	Unlbl	1344130	0	lab	43PR	10279	0.304
Pre-x2 -21.020	0.043	0.044	Unlbl 0.038	1344130 0.041	8.69	lab	43PR	10279	0.040
Post-x2 -20.969	0.043	0.046	Unlbl 0.036	1344130 0.041	8.69	lab	43PR	10279	0.040
Pre-y1 -21.020	022895	A	Unlbl	1344130	8.69	lab	43PR	10279	0.040
Post-y1 -21.072	0.043	0.046	0.038	1344130 0.041	8.69	lab	43PR	10279	0.039
Pre-z2 -12.013	030295	A	Unlbl	1344130	0	lab	43PR	10279	0.315
Pre-z2 -21.020	0.043	0.043	Unlbl 0.036	1344130 0.040	8.97	lab	43PR	10279	0.040
Post-z2 -21.178	0.042	0.045	Unlbl 0.036	1344130 0.040	8.97	lab	43PR	10279	0.038
Pre-x2 -11.864	022895	B	11/9	1340113	0	10/12	44PR	10278	0.326
Pre-x2 -21.072	0.043	0.044	11/9 0.036	1340113 0.040	9.08	10/12	44PR	10278	0.039
Post-x2 -21.125	0.041	0.043	11/9 0.034	1340113 0.039	9.08	10/12	44PR	10278	0.039
Pre-y1 -21.125	022895	B	11/9 0.034	1340113 0.039	9.08	10/12	44PR	10278	0.039
Post-y1 -21.125	0.041	0.044	11/9 0.034	1340113 0.0386	9.08	10/12	44PR	10278	0.039
Pre-z2 -11.574	030295	B	11/9	1340113	0	10/12	44PR	10278	0.348
Pre-z2 -21.125	0.042	0.044	11/9 0.034	1340113 0.039	9.47	10/12	44PR	10278	0.039
Post-z2	030295	B	11/9	1340113	9.47	10/12	44PR	10278	0.037

Data for Second Vibration Test

-21.286	0.040	0.042	0.034	0.038	0.008						
PostVib2	030295	A	-	-	-	-	-	41RP	10279	0.341	
-11.667	0.345										
PostVib2	030295	A	-	-	-	-	-	41PR	10279	0.322	
-11.907	0.325										
PostVib2	030295	A	-	-	-	-	-	42RP	10279	0.655	
-8.828	0.655										
PostVib2	030295	A	-	-	-	-	-	42PR	10279	0.685	
-8.634	0.689										
PostVib2	030295	A	-	-	-	-	-	43RP	10279	0.550	
-9.584	0.555										
PostVib2	030295	A	-	-	-	-	-	43PR	10279	0.518	
-9.850	0.521										
PostVib2	030295	A	-	-	-	-	-	44RP	10279	0.726	
-8.380	0.730										
PostVib2	030295	A	-	-	-	-	-	44PR	10279	0.669	
-8.736	0.673										
PostVib2	030295	A	-	-	-	-	-	C60-C9	10279	0.898	
-7.456	0.903										
PostVib2	030295	B	-	-	-	-	-	41RP	10279	0.321	
-11.926	0.326										
PostVib2	030295	B	-	-	-	-	-	41PR	10279	0.322	
-11.907	0.326										
PostVib2	030295	B	-	-	-	-	-	42RP	10279	0.679	
-8.670	0.684										
PostVib2	030295	B	-	-	-	-	-	42PR	10279	0.683	
-8.643	0.688										
PostVib2	030295	B	-	-	-	-	-	43RP	10279	0.541	
-9.651	0.547										
PostVib2	030295	B	-	-	-	-	-	43PR	10279	0.546	
-9.617	0.550										
PostVib2	030295	B	-	-	-	-	-	44RP	10279	0.637	
-8.948	0.641										
PostVib2	030295	B	-	-	-	-	-	44PR	10279	0.898	
-7.456	0.626										
PostVib2	030295	B	-	-	-	-	-	C60-C9	10279	0.911	
-7.393	0.916										

Table of Contents



[Index of Appendix A](#)



[Up to TVA Homepage](#)



[Back to the Library](#)

Webster: Melanie.Ott@gsfc.nasa.gov 