
Space Shuttle Program Tin Whisker Mitigation

Keith Nishimi - United Space Alliance, LLC

International Symposium on Tin Whiskers

University of Maryland - CALCE

April 24-25, 2007

Copyright © 2007 by United Space Alliance, LLC. These materials are sponsored by the National Aeronautics and Space Administration under Contract NAS9-20000 and Contract NNJ06VA01C. The U.S. Government retains a paid-up, nonexclusive, irrevocable worldwide license in such materials to reproduce, prepare, derivative works, distribute copies to the public, and perform publicly and display publicly, by or on behalf of the U.S. Government. All other rights are reserved by the copyright owner.

Agenda

- Introduction
- Background
- Flight Control System
 - Initial Findings
 - Photos: Whiskers in Avionics Box
 - Tiger Team
 - FCS Conclusions
 - FCS Remediation Plan
- FCS Flight Rationale
- Additional High Criticality Hardware
- Conclusion

Introduction

- **Space Shuttle Program implemented tin whisker (TW) remediation strategy following discovery of TW in Orbiter hardware**
- **Complex investigation and planning involved cooperation among many disciplines and geographic locations**
- **Overall goal to arrive at two products:**
 1. **Flight rationale (should we fly near-term flights with TW?)**
 2. **Plan for TW removal/mitigation (what is long-term plan for removal of TW?)**
- **What was the project management decision-making process?**

Background




- In March 2006, a Flight Control System (FCS) avionics box failed during vehicle testing, and was routed to the NASA Shuttle Logistics Depot for testing and disassembly
- Internal inspection of the box revealed TW growth visible without magnification
- Among hundreds of electrical boxes on the Space Shuttle, the particular type of box with the initial finding of TW is populated 4 per vehicle
- The family of similarly designed boxes is populated 12 per vehicle

Initial Finding

- Whiskers grew from pure tin plated circuit card retainers, not from electrical components
 - Intent of tin plating in original design was for corrosion protection of BeCu retainers
- Immediate Concerns:
 - All FCS avionics boxes in the same family were similarly designed and could fail because of TW
 - Whiskers could either grow into conformal coating, or touch electrical components having inadequate coating
 - Active concern for July 2006 launch; particularly if no clean spares exist to rotate into vehicle
 - How can the Program ensure that other Space Shuttle hardware isn't at high risk for TW failures?

Internal Photos of Tin Whisker Growth

- Box with cover removed illustrates progressively finer detail



Tiger Team Formed

- **NASA formed multi-disciplinary Tiger Team to investigate extent of findings and develop recommendations**
- **Two Branches of Team's Investigation:**
 1. **Detailed investigation of Flight Controls H/W from same vendor (12 per vehicle)**
 2. **Broad investigation of 100+ other high-criticality Orbiter H/W**
- **Functional diversity: design engineering, logistics, test engineering, materials & processes (M&P), ground operations, research**
- **Geographic and corporate diversity: multiple NASA centers (JSC/KSC/GSFC), prime and major subcontractor sites, hardware vendor and supplier**

FCS Conclusions

- Can TW concern be segregated by s/n?
- Quantity of FCS boxes:
 - 52 total quantity across fleet = 12 per vehicle + spares
 - All from same manufacturer, using same card retainer design
- Sampled 15 of the 52 boxes across four different types:
 - 1 & 2) Reaction Control Jets for on-orbit maneuvering (Fwd & Aft)
 - 3) Flight Control Surfaces (e.g. elevons, rudder)
 - 4) Main Engine and Solid Rocket Booster directional control
- All box types high criticality (Crit. “1/1” and “1R”)
- TW only growing from card retainers; up to 18 mm
- Some loose TW present
- Newer-build boxes (~1989) from Endeavour's initial assembly generally contain longer and more dense TW growth
- One box found to have no tin plating on card guides

FCS Conclusions

- **Conformal Coating:**
 - Coating cannot completely prevent TW growth into coating, but lowers likelihood of contact with underlying electronics
 - Some circuit cards found to have incomplete conformal coating due to "shadowing" of spray-on technique
- **M&P investigated sampled cross-sections of card retainers under scanning electron microscope**
 - Plating method cannot exonerate TW boxes
 - More prominent TW growth in newer Endeavour-era boxes could not be correlated with processing variables such as plating material, time, temperature, pressure, etc.
 - M&P recommends 100% inspection
 - Tin plating not needed to prevent corrosion of card retainers

FCS Conclusions

- **Assessment of vendor's build records could not exonerate/segregate boxes**
- **Design team's position:**
 - **51 boxes still at risk**
 - **Based on component layout on circuit cards, even the shorter whiskers (~2 mm) are long enough to cause failure**

FCS Remediation Plan

- Remediation plan developed:
 - Avionics Lab: Remove tin plating and TW
 - Expedite procurement of non-plated card retainer assemblies from vendor
 - Cycle boxes through Lab
 - Incoming testing, disassembly / card removal
 - Assess gross order-of-magnitude quantity of loose whiskers
 - Clean chassis and circuit cards
 - Cards pass magnified inspection
 - Conformal coating touch-up via brush coating as needed
 - Reassemble with non-plated card retainers
 - Full acceptance testing at box level: vibration, thermal, functional
 - Flight Operations: Prioritize Reaction Control Jet firing to minimize likelihood of critical risks

FCS Remediation Plan

- **Plan phased in over multiple years/flights**
 - **Flight Controls design team tracks 51 boxes rotating through remediation plan**
 - **Higher criticality (non-redundant) boxes given schedule priority over redundant boxes**
 - **Pace of plan accommodates Avionics Lab staffing level, quantity of test stations (2), and diversion of equipment and personnel for unrelated failures on same boxes**

Outline of FCS Flight Rationale

- **Is it safe to fly non-repaired FCS boxes?**
 - Remediation of all boxes prior to flight would result in significant delays for Space Shuttle and International Space Station programs
- **Jet Drivers (high criticality / non-redundant)**
 - Inadvertent jet firing concern: risks loads on or contact with Space Station
 - TW-caused inadvertent jet firing is not spontaneous; must be coupled with a commanded jet firing
 - Loose TW needs to bridge specific pin combinations; simultaneously avoiding other pin combinations that can vaporize TW
 - Prioritized jet selection to minimize likelihood of plume and contact loads for Space Station
 - Software limits worst case duration of inadvertent firing to very short duration
 - Installed unique box containing non-plated card guides

Outline of FCS Flight Rationale

- **Control Surface & Engine Directional Control**
 - System architecture mitigates catastrophic failure via hardware redundancy
 - Dual-redundant failure mode requires identical failures to occur within small duration window
- **General Rationale**
 - Conformal coating protects circuits
 - Loose TW would need to migrate from growth sites to critical "smart" locations on circuit cards
 - Sampling of quantity of loose whiskers in three boxes led to belief that actual quantity is small, not large

Additional High Criticality H/W

- Tiger Team assessed other high criticality H/W:
 - Listing of high criticality H/W screened through Materials database of as-built configuration, searching for pure tin
 - List of essential questions distributed to design teams responsible for H/W at risk for pure tin
- Types of criteria:
 - Conformal coating, solder coverage on leads, physical separation, worst case effects having lesser criticality, history of inspections, history of unexplained anomaly trends
- Some H/W inspections authorized

Additional High Criticality H/W

- Findings on two high criticality boxes:
 - Some short TW found on tin plated eyelets on circuit cards
 - Corrective Action: conformal coating applied to eyelets without removal of circuit cards
 - One design allowed for either tin plated rivets or solid aluminum rivets on chassis
 - Spectroscopy performed on large sample of boxes verified solid aluminum rivets

Conclusion

- Program elected to fly with tin whiskered avionics hardware in parallel with implementing remediation plan and adopting operational controls
- TW growth in programs with high reliability standards such as human spaceflight can result in lengthy and costly investigations and remediation plans
 - Remediation plan phased in for flight: July 2006, Sept. 2006, Dec. 2006, and STS-117
 - TW remediation plan continues into CY2009
 - No failures to date positively attributable to TW
- As electrical components adopt lead-free philosophy, caution should be taken when designing and procuring new hardware
- Design decisions can have unintended consequences
- Development and refinement of TW mitigation techniques will benefit programs that have future TW findings