

The logo for HRLabs is a circular emblem. It features the text "HI-REL" at the top and "LABORATORIES" at the bottom. In the center, the letters "hrl" are written in a stylized, lowercase font. The entire logo is rendered in a light green color and serves as a background watermark for the slide.

COTS Trends in DPA Results from 2020

Presented By: Trevor A. Devaney


Presented to: NEPP ETW

June 16

trevor.d@hrlabs.com




2020 DPA PART TYPE DISTRIBUTION






2020 DPA PART TYPE DISTRIBUTION






TRADITIONAL VS. PLASTIC COUNTERPARTS






2020 DPA DISPOSITION BREAKOUT 4206 COMPLETED ANALYSES






2020 DPA FAILURE RATES PER PART TYPE






HISTORICAL DPA FAILURE RATE COMPARISON






**MICROCIRCUITS
FAILURE DISTRIBUTION (136 FAILURES OUT OF 700 DPAS)**






MICROCIRCUITS FAILURE TYPE COMPARISON






TRANSISTORS
FAILURE DISTRIBUTION (47 FAILURES OUT OF 274 DPAS)






TRANSISTORS FAILURE TYPE COMPARISON






DIODES FAILURE DISTRIBUTION (45 FAILURES OUT OF 435 DPAS)






DIODES FAILURE TYPE COMPARISON






RESISTORS FAILURE DISTRIBUTION (58 FAILURES OUT OF 718 DPAS)






RESISTORS FAILURE TYPE DISTRIBUTION






CAPACITORS FAILURE DISTRIBUTION (52 FAILURES OUT OF 791 DPAS)






CAPACITORS FAILURE TYPE DISTRIBUTION






HYBRIDS FAILURE DISTRIBUTION (103 FAILURES OUT OF 316 DPAS)








HYBRIDS FAILURE TYPE DISTRIBUTION






COTS – External PMA Failures



A high tin content surface finish (≥ 97 wt%) was the primary cause of external PMA failures. This surface finish is susceptible to whisker growth.




COTS – Radiography Failures



Majority of radiography failures are a result of embedded foreign/extraneous material within the encapsulant. The risk associated with this condition is likely minimal.



COTS – SAM Failures



Majority of SAM failures have an ingress path from the outside world to the internal construction features. These pathways can potentially allow for manufacturing or end-use environmental elements to contact sensitive features within the device resulting in leakage, corrosion, etc. This is a particular concern with copper wire bonded devices.